

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

HAER  
VA,  
7-ALEX,  
184-

FORD MOTOR COMPANY PLANT  
700 South Union Street  
Alexandria  
Alexandria County  
Virginia

HAER No. VA-123

Bill Lebovich, Photographer


June 28 and 30, July 1, 1996


- VA-123-1 FROM DORY, LOOKING SOUTHWEST AT NORTH SIDE AND EAST FRONT
- VA-123-2 FROM DORY, CLOSER VIEW, LOOKING SOUTHWEST AT NORTH SIDE AND PART OF EAST FRONT
- VA-123-3 FROM DORY, DISTANT VIEW, LOOKING NORTHWEST AT EAST FRONT AND SOUTH SIDE
- VA-123-4 FROM DORY, CLOSER VIEW, LOOKING NORTHWEST AT EAST FRONT AND SOUTH SIDE
- VA-123-5 FROM PIER, LOOKING SOUTHWEST AT ORIGINAL NORTH SIDE AND EAST FRONT
- VA-123-6 FROM PIER, DETAIL OF ORIGINAL NORTH SIDE DOOR BAY
- VA-123-7 FROM PIER, LOOKING NORTHWEST AT EAST FRONT AND SOUTH SIDE
- VA-123-8 FROM SHORE, LOOKING NORTH AT SOUTH SIDE
- VA-123-9 FROM SHORE, LOOKING NORTHEAST AT SOUTH AND CORNER OF WEST SIDE
- VA-123-10 FROM PIER, DETAIL OF DOORS (6<sup>TH</sup> BAY FROM WEST) ON SOUTH SIDE
- VA-123-11 FROM SHORE, LOOKING EAST AT WEST SIDE
- VA-123-12 FROM SHORE, LOOKING SOUTH AT ORIGINAL NORTH SIDE; WEST SIDE OF CIRCA 1954 NORTH ADDITION AT LEFT
- VA-123-13 FROM SHORE, LOOKING EAST AT WEST SIDE OF CIRCA 1954 NORTH ADDITION; ORIGINAL NORTH SIDE AT RIGHT
- VA-123-14 FROM SHORE, LOOKING SOUTHEAST AT NORTHWEST CORNER OF CIRCA 1954 NORTH ADDITION

- VA-123-15 FROM SHORE, DETAIL LOOKING EAST AT DETERIORATED SLAB OF CIRCA 1954 NORTH ADDITION
- VA-123-16 FROM SHORE, DISTANT VIEW LOOKING SOUTHEAST AT NORTH SIDE
- VA-123-17 FROM ROOF OF ADMINISTRATION BUILDING, LOOKING NORTH
- VA-123-18 FROM ROOF OF ADMINISTRATION BUILDING, LOOKING WEST AT ROOF OF SERVICE BUILDING
- VA-123-19 FROM ROOF OF SERVICE BUILDING, LOOKING NORTH; ADMINISTRATION BUILDING AT RIGHT
- VA-123-20 FROM ROOF OF SERVICE BUILDING, DETAIL VIEW OF 2<sup>ND</sup> STORY WEST SIDE OF SOUTH CORNER OF ADMINISTRATION BUILDING
- VA-123-21 FROM ROOF OF SERVICE BUILDING, LOOKING WEST ALONG NORTH EDGE
- VA-123-22 FROM ROOF OF SERVICE BUILDING, LOOKING NORTHEAST AT LIGHT MONITORS OF CENTRAL AND SOUTH BAYS
- VA-123-23 FROM ROOF OF SERVICE BUILDING, LOOKING SOUTHEAST AT LIGHT MONITOR OF CENTRAL BAY; WINDOWS ARE ANGLED OPEN
- VA-123-24 INTERIOR, ADMINISTRATION BUILDING, 2<sup>ND</sup> FLOOR OFFICES, LOOKING NORTH; NOTE GLASS (BROKEN) TRANSOM, WHICH OPENS, BETWEEN CORRIDOR AND OFFICE
- VA-123-25 INTERIOR, ADMINISTRATION BUILDING, 2<sup>ND</sup> FLOOR CORRIDOR, LOOKING NORTH; NOTE LIGHTING FIXTURE IN COVED CEILING
- VA-123-26 INTERIOR, ADMINISTRATION BUILDING, 2<sup>ND</sup> FLOOR CORRIDOR, LOOKING SOUTH TOWARDS STAIRS
- VA-123-27 INTERIOR, ADMINISTRATION BUILDING, 2<sup>ND</sup> FLOOR, SOUTHEAST CORNER SPACE, LOOKING UP AT CIRCULAR MOTIF AND BANDS IN THE CEILING ABOVE THE ACOUSTICAL TILES
- VA-123-28 INTERIOR, ADMINISTRATION BUILDING, 2<sup>ND</sup> FLOOR STAIRS, LOOKING SOUTH
- VA-123-29 INTERIOR, ADMINISTRATION BUILDING, STAIR LANDING, LOOKING NORTHEAST AT CIRCULAR MOTIF IN LOBBY CEILING AND CORNICE DETAIL

- VA-123-30 INTERIOR, ADMINISTRATION BUILDING, 1<sup>ST</sup> FLOOR LOBBY, LOOKING WEST AT STAIRS
- VA-123-31 INTERIOR, SERVICE BUILDING, FROM NORTHEAST CORNER LOOKING WEST ALONG THE NORTH BAYS; ORIGINAL NORTH WALL AT RIGHT
- VA-123-32 INTERIOR, SERVICE BUILDING, LOOKING SOUTH FROM NORTHEAST CORNER TOWARDS PAINTING ROOM
- VA-123-33 INTERIOR, SERVICE BUILDING, LOOKING WEST FROM SOUTHEAST CORNER ALONG SOUTH BAYS
- VA-123-34 INTERIOR, SERVICE BUILDING, LOOKING NORTHEAST FROM SOUTHWEST CORNER TOWARDS CENTRAL BAYS
- VA-123-35 INTERIOR, SERVICE BUILDING, LOOKING UP FROM WEST AT TRUSSES IN CENTRAL BAY
- VA-123-36 INTERIOR, SERVICE BUILDING, DETAIL VIEW LOOKING UP FROM WEST AT TRUSSES IN CENTRAL BAY
- VA-123-37 INTERIOR, SERVICE BUILDING, DETAIL VIEW LOOKING UP FROM WEST AT TRUSSES AND PIER CONNECTIONS IN CENTRAL AND SOUTH BAYS
- VA-123-38 INTERIOR, SERVICE BUILDING, LOOKING AT NORTHWEST CORNER FROM WEST END OF CENTRAL BAY
- VA-123-39 INTERIOR, SERVICE BUILDING, LOOKING NORTH IN ROOM PARTITIONED AT SOUTHWEST CORNER OF BUILDING
- VA-123-40 INTERIOR, SERVICE BUILDING, CIRCA 1954 NORTH ADDITION, LOOKING EAST; ORIGINAL EXTERIOR NORTH WALL AT RIGHT
- VA-123-41 INTERIOR, SERVICE BUILDING, CIRCA 1954 NORTH ADDITION, LOOKING WEST; ORIGINAL EXTERIOR NORTH WALL AT LEFT
- VA-123-42 INTERIOR, SERVICE BUILDING, CIRCA 1954 NORTH ADDITION, DETAIL VIEW LOOKING SOUTHWEST AT EAST END OF ORIGINAL EXTERIOR NORTH WALL

FORD COMPANY MOTOR PLANT  
 HAER No. VA-123  
 Key to Photographs  
 (Page 4)





FORD COMPANY MOTOR PLANT  
 HAER No. VA-123  
 Key to Photographs  
 (Page 6)

